Contents

=	annin E	ilementary	2
	Gener	ral comments, campus capacity, and student demographics	2
		School Site	
	2.0	Building Systems and Components	5
	3.0	Building Safety and Security	9
	4.0	Educational Adequacy	12

Fannin Elementary



General comments, campus capacity, and student demographics

General comments:

Fannin Elementary campus was originally constructed in 1954 with additions in 1970 and 1981 and an addition and major renovation in 2000. The campus is comprised of about 73,000 square feet and rests on approximately 4.9 acres. There are currently 606 students enrolled, Pre-K through 5th grades, and 71 staff. The buildings are generally in good condition, but due to their age there are pressing maintenance and repair issues that need to be addressed.

urrent Enrollment:	Pre-K	0
	Kinder	91
	1st	108
	2nd	90
	3rd	95
	4th	120
	5th	91

of Permanent General Instruction Classrooms: 31 (excludes portable bldgs., science and PC labs, and specialized learning areas)

Total:

Maximum # of Students per Classroom: 22

Maximum # of Students - Campus: 682 (without utilization factor)

Utilization Factor: 0.95 (to allow enrollment and program fluctuation)


595

of Students Over Capacity: 048


Of Students Over Capacity: 048

| % Capacity: 048

		10 Year Historical Elementary Enrollment									
Grade	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	
Pre-K	0	0	0	0	0	0	0	0	0	0	
Kinder	110	107	106	85	83	84	86	90	97	89	
1st	110	128	111	110	97	100	110	87	78	108	
2nd	97	105	133	111	108	97	104	114	82	94	
3rd	132	93	100	118	110	110	107	107	106	94	
4th	124	133	98	96	118	117	115	104	96	120	
5th	113	128	121	98	94	105	120	115	92	96	
Total	686	694	669	618	610	613	642	617	551	601	
Growth %	N/A - Base Year	1.17%	-3.60%	-7.62%	-1.29%	0.49%	4.73%	-3.89%	-10.70%	9.07%	
Student Growth	N/A - Base Year	8	(25)	(51)	(8)	3	29	(25)	(66)	50	



		10 Year Projected Elementary Enrollment										
Grade	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023		
Pre-K	0	0	0	0	0	0	0	0	0	0		
Kinder	87	85	84	82	80	79	77	76	74	73		
1st	88	87	85	83	81	81	80	80	79	78		
2nd	109	89	87	86	84	85	86	86	87	88		
3rd	93	107	88	86	84	83	82	80	79	78		
4th	95	94	109	89	87	88	89	90	91	92		
5th	120	95	93	108	88	88	88	87	87	87		
Total	592	557	546	534	506	503	501	500	498	496		
Growth %	-1.54%	-5.90%	-2.03%	-2.15%	-5.29%	-0.41%	-0.40%	-0.38%	-0.37%	-0.35%		
Student Growth	(9)	(35)	(11)	(12)	(28)	(2)	(2)	(2)	(2)	(2)		



1.0 School Site

Parking and Drives

-

Area	Regular Spaces	ADA	Van Accessible	Surface Type	Surface Condition	Striping Condition	Lighting
South	10	1	0	Asphalt	Fair	Good	N/A
North	72	4	4	Asphalt	Poor	Good	Good
Total	82	5	4				
al recommended/required	101	4	2				
Difference (//)	(10)	. 1	. 2	İ			

Parking based on:

Staff

606 Students

71

- Asphalt failure at South service entrance apron. All asphalt surfaces need to be rebuilt.



- No designated visitor parking at south or main entrance for visitors.
- Non-hard surface parking for staff at northwest.



2.0 Building Systems and Components

ADA Accessibility

- Hand rails at portable building ramps are not compliant.
- Main building Some parking spaces/slopes, routes from parking and building to building are not ADA accessible.
- Portable Signage, some door levers, restrooms, and drinking fountains.

Roofs

- Staff reporting windows in connecting hall leak, connecting hall is between Wing C and the original building.
- Administration Wing original roof minor granule loss, minor ponding;
 approximately 5 years of life left.



- Administration Wing Original Roof – Clogged gutter at front of building can cause runoff to seep into fascia.



- Administration Wing original roof – Cypress tree over roof and needles piling up at drains and filling gutter and oak on southwest side; major ponding.




- Classrooms – Leaks in Room D-103 at air conditioning penetration; leak in Room D-110 at southeast wall; leak in Room C-110 from air conditioning vent.

Foundations

- Southwest corner of cafeteria; some cracks at northwest of Main Building (3 locations).



- Cracks at northeast of 2000 addition - no erosion.



No splash blocks – east side of 2000 addition – erosion occurring.



Interior CMU crack in hall by Room A-105



Building Envelope

- Gym and portable are single-pane windows and should be considered for replacement during next major renovation.

Drinking Fountains

-

Location	Quantity	ADA
D Hall	1	1
C Hall	2	2
B Hall	1	0
A Hall	1	0
Cafeteria	1	1
Gym	2	2
Portable	1	0
Totals	9	6

+ / (-) Recommended * + 6

+ 2

Restrooms

-

Student

Campus/Location	Boys Commodes	ADA Boys Commodes	Urinals	Sinks	ADA Sinks	Girls Commodes	ADA Girls Commodes	Classroom/Unisex Commodes	ADA Classroom/Unisex Commodes
D Hall	2	1	4	4	3	6	2		
C Hall	3	1	3	3	3	6	2		
B Hall	1	1	2	6	0	3	1		
Cafeteria	1	1	1	2	0	1	1		
Gym	1	1	3	4	4	4	1		
Portable				3				3	
Totals	8	5	13	22	10	20	7	3	0
+ / (-) Recommended	+ 2		+ 3	+ 15		+ 13			-

Staff

Starr									
Campus/Location	Men's Commodes	ADA Men's Commodes	Urinals	Sinks	ADA Sinks	Women's Commodes	ADA Women's Commodes	Unisex Commodes	ADA Unisex Commodes
Front Office	1	1		3	1	2	1		
Cafeteria Kitchen				1				1	
Totals	1	1	0	4	1	2	1	1	0

Exterior Windows, Doors, and Walls

- Main Building some cracks in walls
- Portables door finish in poor condition
- Repaint wood soffits and fascia
- Leaking gutters stains north side



- Gym doors chipping and oxidized





Portables skirting paint chipping



Flooring

- Carpet installed in 1999
- A Hall, B Hall, C Hall, D Halls and Classrooms Carpet in bad condition visible seams, stained
- Portables Carpet in bad condition stained


Interior Doors, Cabinets, Ceilings and Walls

- Cafeteria ceiling bowed and discolored
- Portable ceiling Bowed, discolored and mismatched

3.0 Building Safety and Security

Student Loading Areas

_



- No canopy at parent pickup location on West.
- Parents pick up on the west side from the entrance near the main office and the hall near the library. There is only enough space for 13 vehicles to stack off of the right- ofway. Cars will stack for over 500 feet beyond the fire station on N Beaton Street across W College Ave.
- Buses pickup on the northeast side.

Playgrounds and Athletic Field Equipment

- No secure fence or shade canopy to protect students and equipment from the elements.
- North Playground inadequate fall material (average depth ½")
- Insufficient playground equipment for student enrollment

Limited equipment – North



Limited equipment – South



Campus Security Systems

- Campus not fenced with secure gates.
- No interior or exterior security cameras
- No secure vestibule.
- Main Building no security lights on north side of building
- Burglar alarm only covers 40-50% (covers PC Lab) but not back half of building. Portables also have burglar alarm. Cafeteria and Gym do not have a burglar alarm.

Life Safety Systems

- Cafeteria No pull stations, wall packs Emergency lights, smoke detectors, heat sensors, or sprinkler.
- Main building halls No wall packs Emergency lights, or sprinkler.
- Main building classrooms No smoke detectors or heat sensors.
- Main building restrooms No wall packs emergency lights, smoke detectors, or heat sensors.
- Gym No wall packs emergency lights, smoke detectors, heat sensors, or sprinkler.
- Gym restrooms No wall packs emergency lights, smoke detectors, or heat sensors.
- Portables No wall packs emergency lights, smoke detectors, or heat sensors.
- Portables restrooms No strobes, no emergency lights, smoke detectors or heat sensors.

Portable – pull station broken; hand sanitizer is an obstruction below pull station.



4.0 Educational Adequacy

Size of Academic Learning

 Most classrooms do not meet current TEA space requirements of 800 square feet minimum for Pre-K through 1st grades and 700 square feet minimum for 2nd through 5th grades.

Specialized Learning Areas

- 7 specialized classrooms (Speech, Dyslexia, GT, special education, and ISS).

Library/Resource/Media Center

_

# of students	606
Total sq. ft.	1,464
TEA recommended sq. ft.	3,318
+ / (-) TEA recommended	(1,854)
Meets TEA recommended	No
Storage sq. ft.	N/A
Media Center sq. ft.	N/A
Office sq. ft.	Shared
Work Room sq. ft.	N/A
Age approriate	Yes

Gymnasium, Athletic Facilities, P.E. Areas

- Practice gym has 5,070 square feet with a seamless rubber floor.

Science

No designated science lab.

Music Program and Art

- No acoustical wall treatment; shares with art; poor storage.
- Carpet adequate for music but not for art due to spills.

Computer Labs

		+ / (-) TEA 900			
	Square	sq. ft.	Max # of	Current #	PC's + / (-) TEA
Room	feet	requirement	PC's *	of PC's	requirement
B100	961	+ 61	27	30	+ 3

Inadequate PC labs for campus enrollment.

Teachers' Lounge and Work Rooms

- Workroom B101 382 square feet with 1 sink.
- Teacher's Lounge C Hall 350 square feet, 6 seats, 1 sink, 1 microwave, 1 stove, 1 refrigerator, and 1 ice machine.

Cafeteria and Kitchen

- Service drive of Main Entrance (delivery trucks pull into street to backup)



- Loading dock at 21.02% - unsafe for deliveries.



- Congested kitchen and shared office space.







Cafeteria - Seating Area **Serving Area** Square Feet Square Feet -Square Feet Recommended Square Feet -Square Feet -+/(-) Seating Square Feet -+/(-) Actual Recommended * Recommended Capacity Actual Recommended + 1,268 + 142 3,428 2,160 216 250 108

** ½ a square feet per seat * 10 square feet per seat

			Lunch Periods							
Square Feet - Actual	Square Feet - Recommended ***	Square Feet +/(-) Recommended	Storage	Average Daily Meals Served	# of Lunch Periods	Begins at:				
1,675	3,644	(1,969)	Limited	1,041	7	10:45am				
*** 3 ½ saua	*** 3 ½ square feet per meal served									

Nurse's Clinic

Square Feet	+ / (-) recommended	# of Sick Beds / Private	# of Restrooms	Sink	Secure Storage	Near front office
286	(214)	2 / no	1	No	Yes	Yes

Reception Space

Space is 116 square feet with 2 seats. Limited for 600 students.